AN ORDINANCE

BY: TRANSPORTATION COMMITTEE

02- 0 -1921

AN ORDINANCE AUTHORIZING THE MAYOR OR HER DESIGNEE TO INSTALL STOP SIGNS AT THE FOLLOWING INTERSECTION: MARGARET MITCHELL DRIVE, N.W., GREENDALE DRIVE AND HOWELL MILL ROAD.


NOW, THEREFORE, BE IT ORDAINED BY THE COUNCIL OF THE CITY OF ATLANTA, as follows:

<u>SECTION 1.</u> That STOP signs be installed at the following intersection within the City of Atlanta:

On MARGARET MITCHELL DRIVE, N.W. AND GREENDALE DRIVE, N.W. at HOWELL MILL ROAD, making HOWELL MILL ROAD the through street.

<u>SECTION 2.</u> That all ordinances and parts of ordinances in conflict herewith be and the same are hereby repealed.

7	Bureau o	Albilo, Gast	ransportation	ORDINANCE \	/ E X:-
OCATION ,	Phone	Office Letter _	FĂX		Nω
How	ell Mill 1	RO / MARGA	KET MITCHE	u or/GRE	ENOALE
EPORTED BY	SEE	ATTACH	≘ Ŋ		
Organization —					
Address ———					
ONDITION REPO			Date Report	ed	
424 (44)					
ORDINANCE:			GREENDAL		<u>ω.</u>
1					
	INSTALLED	DN ALL	MAY STOP APPROACHES	TO THE	In Telse
CTION TAKEN	voru orde	eva To T	Date Comple	ted 9/26/	32
BARS, 7	3/and, R	PMS +	ARKOWS	TO SIGUE S	
Sigas	#2387				
Marki	#2387 -gs #636	7			
					-
		Handled By _			



3020 Greendale Drive, NW Atlanta, Georgia 30327

September 5, 2002

City of Atlanta
Department of Public Works
Bureau of Traffic and Transportation
55 Trinity Avenue, Suite 4700
Atlanta, Georgia 30303

Attention:

Ms. Sandra Jennings, Manager and

Mr. Randy Bundy, Manager

Ladies and Gentlemen:

I would like to notify you of my concerns about the intersection of Greendale Drive, Margaret Mitchell Drive and Howell Mill Road. This intersection presents an extremely dangerous situation. I have nearly had several accidents there and have witnessed many nearmisses.

Cars traveling east on Margaret Mitchell Drive essentially do not have a stop sign, which presents a danger to traffic coming from Greendale Drive as well as traffic traveling south on Howell Mill, especially traffic attempting to turn right onto Greendale from Howell Mill. Furthermore, when turning left onto Greendale Drive when traveling north on Howell Mill Road, one cannot see the oncoming traffic coming around the curve (heading south on Howell Mill Road) until the last minute. One must come to a full stop before turning, which invariably surprises (and angers) cars in the rear, thus causing additional risk.

I would appreciate your giving this situation a full analysis and your reporting back to me in writing at your earliest convenience as to your conclusions. I believe that the traffic plan for the intersection needs serious attention before someone is seriously injured or killed.

Thank you for your attention to this request.


Very truly yours,

GLS/aq

J. Leighton Stradtman

Ephrain 9/11/02

Print this page using the print function in your browser.






© 2002 Microsoft Corporation and/or its suppliers. All rights reserved.
© 2000 Navigation Technologies. All rights reserved.
© Copyright 2000 by AND Data B.V. All rights reserved.
© Copyright 2000 by Compusearch Micromarketing Data and Systems Ltd. All rights reserved.
© 2000 Geographic Data Technology, Inc. All rights reserved.

Expedia, Inc., not responsible for content on external Web sites.©2002 Expedia, Inc. All rights reserved.

Print this page using the print function in your browser.






© 2002 Microsoft Corporation and/or its suppliers. All rights reserved.
© 2000 Navigation Technologies. All rights reserved.
© Copyright 2000 by AND Data B.V. All rights reserved.
© Copyright 2000 by Compusearch Micromarketing Data and Systems Ltd. All rights reserved.
© 2000 Geographic Data Technology, Inc. All rights reserved.

Expedia, Inc., not responsible for content on external Web sites ©2002 Expedia, Inc. All rights reserved.



Print this page using the print function in your browser.



© 2002 Microsoft Corporation and/or its suppliers. All rights reserved.

© 2000 Navigation Technologies. All rights reserved.

© Copyright 2000 by AND Data B.V. All rights reserved.

© Copyright 2000 by Compusearch Micromarketing Data and Systems Ltd. All rights reserved.

© 2000 Geographic Data Technology, Inc. All rights reserved.

Don't just travel. Travel Right:

Expedia, Inc., not responsible for content on external Web sites@2002 Expedia, Inc. All rights reserved.

TRANSMITTAL FORM FOR LEGISLATION

10: Gre	eg Pridgeon, Office of the Mayor		2/24	
From: Department of Public Works		Contact (Names):	José Banda 404-330-6501	
Commission	oner's Signature: Jun W. Danff	Manager's Signature: mendely		
Committee	e(s) of Purview: Transportation	Committee Deadli	ine: 10/28/02	
Committee	e Meeting Date(s): 11/13/02 & 11/27/09	2 City Council Meet	ing Date: 11/18/02	
CAPTION:	AN ORDINANCE AUTHORIZING THE INSTALL STOP SIGNS AT THE MARGARET MITCHELL DRIVE, HOWELL MILL ROAD.	E FOLLOWING	INTERSECTION:	
install a Si	UND/PURPOSE/DISCUSSION: Received top sign at Margaret Mitchell Drive, N.W DISTRICT 8).	request dated Sep ., Greendale Drive a	ntember 5, 2002 to and Howell Mill Road	
FINANCIAI	LIMPACT (if any): Cost of STOP sign and	pole = \$42.		
Mayor's St	aff Only		A. a	
Received b	y Mayor's Office: 18/29/02 M (Date)	Reviewed by:(In	nitials) (Date)	
Submitted	to Council: (Date)	_	•	
Action by (Committee: Approved Adversed	Held	Amended	
	Substitute Peferred	Other		